

## ABSTRACT

An adhesion method for a wall hanger paster and a base comprises the steps: spreading liquid glue or dissolvent on the center of the bottom face of the base or melting the bottom face of the base with instant high heat; bending the paster to be an arc shape; and pressing the paster toward the bottom face of the base, the bulgiest point of the center of an arc face connecting to the base, and then gradually pressing the paster to make the paster and the base gradually stick together. An adhesion device for a wall hanger and a base comprises an upper mold and a lower mold. The upper mold has a paster clamping board having holes, a clamping trough, a base holding board having pillars, and the center place of the base holding board having a base installed groove corresponding to the fixing place of the paster.

15